

### TECHNICAL SPECIFICATIONS

| Feature       | Unit                     | Minimum limit | Standard | Maximum limit |
|---------------|--------------------------|---------------|----------|---------------|
| Grams/meter   | g/sq.m                   | 428           | 475      | 523           |
| Width         | inches                   | 45            | 48       | ***           |
| Cutable width | inches                   | 43            | 46       | ***           |
| Fabric Yield  | m/kg                     | 1.51          | 1.74     | 2.03          |
| Ounces/yards  | Oz/sq.yd                 | 12.6          | 14.0     | 15.4          |
| Fiber content | 94% POLYESTER 6% SPANDEX |               |          |               |

Additional comments about technical specifications

Larger width is not considered to be out of specification.

REST TIME 48 HOURS.

Style may contain barre.

### NCM

| PFD        | Off White/White | Dyed       | Printed    |
|------------|-----------------|------------|------------|
| 6004.10.31 | 6004.10.31      | 6004.10.32 | 6004.10.34 |

### DIMENSIONAL STABILITY

| Shrinkage after washing (Machine wash - dry flat %) | Length (%) | Width (%) |
|---|------------|-----------|
|   | 12         | 10        |

Additional comments about dimensional stability

The shrinkage value is an average between the batches produced and may be subject to change.

Do not leave dirty clothes together in a closed place for a long time, always keep separated in a cool and ventilated place.

Separate by light and dark colors. Use neutral soap. Do not twist.

Style subject to shrinkage of up to 12%.

### WASHING INSTRUCTIONS



- maximum temperature for the machine wash 30C (85F) / delicate gentle



- do not bleach



- dry flat



- maximum temperature for the iron heat 110C (230F)



- do not dryclean

### Additional instructions to use with care symbols

### STORAGE INSTRUCTIONS

- Do not hit the ends of the fabric (do not hit the top).
- Keep the packaging of the rolls until their end use.
- The identification of the rolls must always be kept.
- Stored textiles should not be exposed to the light. The exposure will compromise the fabric over time.
- Separate by batch.

### GENERAL COMMENTS

- Neon colors have low resistance to light and washing; they should not be mixed with other colors and / or fabric in the same piece; they should be washed separately.
- The washing mode is performed on the fabric, but after the fabric is converted into clothing, it must be evaluated (clothing appearance, use of other fabrics, use of interfacing / interlinings, etc).
- Be careful of the fabric getting in contact with abrasive surfaces, yarn may be tugged.
- Do not mix batches.
- Claims will be accepted within 15 days after receipt of the goods.
- All tests mentioned above were performed through NBR, ISO, AATCC standards and / or internal standards.

Prepared by ANDREIA: Quality / Kalimo  
Approved by MURILO: Technical Manager